Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number
EDR ID Number

 BE285
 LOT 5,TAXBLOCK 7061
 NY Spills
 \$109942653

 SW
 1718 MERMAID AVENUE
 NY E DESIGNATION
 N/A

1/4-1/2 0.421 mi.

2221 ft. Site 2 of 3 in cluster BE

BROOKLYN, NY 11224

Relative: SPILLS: Higher Name:

Higher Name: CARLOS RODIRIGUES
Actual: Address: 1718 MERMAID AVENUE

5 ft. City,State,Zip: BROOKLYN, NY

Spill Number/Closed Date: 1210153 / 2013-03-27

Facility ID: 1210153 Facility Type: ER DER Facility ID: 427466 Site ID: 473228 DEC Region: 2 Spill Cause: Storm Spill Class: Not reported SWIS: 2401 Spill Date: 2012-11-12 Investigator: Hurricane Sandy R2 Referred To: Not reported Reported to Dept: 2012-11-12 CID: Not reported Water Affected: Not reported

Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Not reported

UST Trust: False

Remediation Phase:

Date Entered In Computer: 2012-11-12 Spill Record Last Update: 2012-11-12

Spiller Name: CARLOS RODIRIGUES
Spiller Company: CARLOS RODIRIGUES
Spiller Address: 1718 MERMAID AVE

Spiller Company: 999

Contact Name: CARLOS RODIRIGUES

DEC Memo: "This spill report was created for tracking purposes related to the

Department's Hurricane Sandy emergency response efforts, pumped out

11/12/2012 by JRG Transport. 500 gallons removed. Barney"

Remarks: "dec on site now for pump out"

All Materials:

Site ID: 473228 Operable Unit ID: 1223077 Operable Unit: 01 Material ID: 2221829 Material Code: 0001A Material Name: #2 fuel oil Case No.: Not reported Material FA: Petroleum Quantity: Not reported Not reported Units: Recovered: 500.00 Oxygenate: Not reported Map ID MAP FINDINGS
Direction

Distance Elevation Site

Site EDR ID Number

EDR ID Number

EDR ID Number

EPA ID Number

E DESIGNATION:

Name: LOT 5,TAXBLOCK 7061
Address: 1718 MERMAID AVENUE
City,State,Zip: BROOKLYN, NY 11224

 Tax Lot(s):
 5

 Tax Block:
 7061

 Borough Code:
 BK

 E-No:
 E-229

 Effective Date:
 7/29/2009

 Satisfaction Date:
 Not reported

 Ceqr Number:
 08DME007K

 Ulurp Number:
 090272ZMK

Zoning Map No: 28d

Description: Hazardous Materials* Phase I and Phase II Testing Protocol

Lot Remediation Date: Not reported